


## Modified HSS Stratocaster® Wiring Diagram

Master Volume (500K Pot)  
Master Tone  
Blender Pot  
(2) 500K Resistors - Connected to Ground

Note: No jumpers are depicted. Make sure all metal is properly grounded.



**Note:** If 3 or 4 Conductor Tape off Red or Red & Green.

**Note 2:** (2) Resistors help Single Coils "see" 250K Pots.